

Rotation	Left	Right	Left	Right
PWM_1 (PWM_4)	"1"	"0"	PWM	"0"
PWM_2 (PWM_5)	"0"	"1"	"0"	PWM
PWM_3 (PWM_6)	PWM	PWM	"1"	"1"
Decay mode	Fast DECAY	Fast DECAY	Slow DECAY	Slow DECAY